

Upgrade instruction about xxx-part1.bin and xxx-part2.bin.docx

DH_XVR5x08-I_MultiLang_PN_V4.000.0000002.13.R.191012-part1.bin (Hereinafter referred to as “xxx-part1.bin”).


DH_XVR5x08-I_MultiLang_PN_V4.000.0000002.13.R.191012-part2.bin (Hereinafter referred to as “xxx-part2.bin”).

This firmware package contains the above two bin files, mainly for compatibility with the upgrade of early and later firmware. The details are as follows:

1. For XVR5x08x-I model: If the firmware version is earlier than October 12, 2019, you can upgrade with xxx-part1.bin.
2. For XVR7x04x-I model: If the firmware version is earlier than October 12, 2019, you have to upgrade with xxx-part1.bin firstly, and then upgrade with xxx-part2.bin according to the prompt. After the xxx-part1.bin has been installed, reboot the device. The prompt interface is displayed. Then follow the instructions to upgrade with xxx-part2.bin.

The Upgrade interface is shown as below. See figure 1.

Figure 1 Upgrade interface



The Web interface is shown as below. See figure 2.

Figure 2 Web interface

