



IVSS V2.004.0000000.2

Release Notes



Legal Information

Copyright

© 2021 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 ,  ,  , and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.

Table of Contents

Legal Information	I
Release Notes	1
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs.....	1
1.4 Compatibility.....	1
1.5 Software Environment	1
1.6 Pending Issues.....	2
1.7 Update Guide	3

Release Notes

1.1 Overview

Item	Description
Product name	Intelligent video surveillance server
Version	V2.004.0000000.2.R
Software package information	DH_IVSS7XX_Eng_V2.004.0000000.2.R.220715
OS requirement	None
Release date	August 2, 2022

1.2 New Features

Feature	Description
None	

1.3 Fixed Bugs

Fixed some bugs

1.4 Compatibility

This version is V V2.004.0000000.2.R, which is compatible with V2.004.0000000.0.R or earlier versions.

1.5 Software Environment

Model	Version
DH-IPC-EBW81230P DH-IPC-EBW81230N	2.6.01.05.17336 DH_IPC-HX8XXX-Nova2_EngSpnFrn_NP_Stream3_V2.622.0000000.9.R.1 91210.zip
DH-IPC-HFW5241TP-AS-P V-0360B	2.6.01.05.24482 DH_IPC-HX5XXX-Volt_MultiLang_PN_Stream3_V2.800.0000000.19.R.200 709.zip

DH-IPC-HFW5241EP-ZE-27135	2.6.01.05.26353 DH_IPC-HX5XXX-Volt_MultiLang_PN_Stream3_V2.800.0000000.20.R.200903.zip
DH-IPC-HF7442FP-FR	2.6.01.05.21691 DH_IPC-HX8XXX-Nobel_MultiLang_PN_V2.800.0000000.5.R.200525.zip
DH-IPC-PFW83242N-A180-E4	2.6.01.05.27624 DH_IPC-PFW832XX-Fafnir_MultiLang_NP_Stream3_V2.800.0000000.2.R.200927.zip
DH-PSDW81642M-A360-D440 DH-PSDW8842M-A180-D440	2.6.01.05.26094 DH_IPC-PSDW8XXXL-Fafnir_EngSpnFrn_PN_Stream3_V2.800.0000000.3.R.200828.zip
IPC-HDW8341XN-3D-0280B-S2	2.6.01.05.28259 DH_IPC-HX8XXX-Dual-Lens-Nobel_MultiLang_NP_V2.800.0000000.12.R.201022.zip
DH-SDT5X425-4Z4-WA-2812	2.6.01.05.22787 DH_SD-Fafnir_MultiLang_PN_Stream3-LingxiV2_V2.810.0000008.2.R.200603.zip
DH-TPC-BF1241	2.6.01.05.27812 DH_TPC-BF1241-TB_MultiLang_NP_V2.630.0000000.0.R.201013.zip
DH-TPC-PT8421A	2.6.01.05.24525 General_TPC-PT8X21A-TB_MultiLang_PN_V2.630.0000000.3.R.200721.zip
DHI_ITC215_PW6M_IR_LZF	2.6.01.08.05976 General_ITC215-PW6M-XXX_Eng_PN_Oversea_ITCPUSH_Europe_V2.623.0000000.0.R.200521.zip
ITC952_AU3F_IRL	2.6.01.08.05590 General_ITCX52-AF3F_Eng_P_Oversea_V2.822.0000000.0.R.200414.zip
ConfigTool	2.8.02.01.00366 General_ConfigTool_ChnEng_V4.011.0000003.6.R.20200114.zip
DSS PRO	2.7.01.02.02126 General_DSS-Pro_Win64_IS_V8.000.0000001.0.R.20201215.exe
DMSS	v1.91.001

1.6 Pending Issues

None.

1.7 Update Guide

The product supports update by ConfigTool/PC client/USB flash disk. Do not power off during the update. All intelligent transactions will be suspended during the update. For specific operation procedures, see *Intelligent Video Surveillance System Update Guide*.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com